



Oppdragsgiver Client

BEWI Norplasta AS Postboks 3009 Lade 7441 TRONDHEIM NO Utførende enhet/lab. Department/laboratory responsible

Kiwa AS

Materials Technology

P.O.Box 1019

NO - 3601 KONGSBERG

Rapportnr. Report no.

3000-21-100093

Tittel Title

Testing at BEWI Norplaste AS of BEWI Smart universal protectors

Dato Date 11.06.2021	Utarbeidet av Prepared by Mona Kirksæther	Godkjent av Approved by Asgeir Haukaas	Innleveringsdato for prøve Date of receipt of test object 27.05.2021	
			Prøvetaking utført av Kiwa Sampling by Kiwa	
			Nei <i>No</i>	
Revisjonsnr. Revision no.	Konfig.kont. Config.contr. Antall sider No. of pages		Ant. vedlegg No. of append.	
: -	Ja Yes	21	0	
Kopi nr. Copy no.	Akkreditert test (ISO 17025) Accredited test (ISO 17025) Nei No	Kundens ref. Client's ref. Mads Bugge Amundsen	Bestillingsnr. Order no.	

Fordeling Distribution

Original (pdf): BEWI Norplasta AS

Copy 1: Kiwa/3000

Prøvingsresultater gjelder utelukkende de prøvede objekter. Utdrag av rapporten må ikke gjengis uten skriftlig godkjenning fra Kiwa Teknologisk Institutt as.

Test results relate only to the items tested. The report shall not be reproduced except in full, without the written approval of the laboratory.

SK-0016 d - N/E

Kiwa AS





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 2 av of 21 Dato Date 11.06.2021



Contents

0		ope	
2 3		ceptance criteria and test specificationference Documents	
4		st Procedure	
	4.1	Test samples	
	4.2	Exposure to temperature before testing	4
	4.2	.1 Equipment and conditions	4
	4.3	Axial impact test	5
	4.3	.1 Equipment	5
	4.3	.2 Procedure	6
	4.4	Angular impact test	6
	4.4	.1 Equipment	6
	4.4	.2 Procedure	7
	4.5	Vibration test	8
	4.5	.1 Equipment	8
	4.5	.2 Procedure	8
	4.6	Stripping test	8
	4.6	.1 Equipment	8
	4.6.	.2 Procedure	9
5		sults	10
	5.1	Axial impact test	10
	5.2	Angular impact test	15
	5.3	Lateral impact test	19
	5.4	Vibration	19
	5.5	Stripping test	20
3	Sur	mmary of the results	21





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 3 av of 21 Dato Date 11.06.2021



1. Scope

Testing was done on site at Bewi Norplasta AS in Trondheim 27.05.21. Kiwa AS was on site on behalf of the client to observe the testing. BEWI Smart protector type Pin and Box in size 5 ½" was tested. See picture 1. The testing that was done was:

- Axial impact
- Angular impact
- Lateral impact
- Vibration test
- Stripping test

The primary function of the tread protector for the pipe ends is to protect the threads and critical sealing areas from impact. This type of damage may occur at any point during the transportation and handling process. From the time the pipe leaves the threading facility until the time the pipe is run downhole at the rig floor, these critical areas must be adequately protected.

The protector is designed to operate in the temperature range of -46 °C (-50 °F) to 66 °C (150 °F). So, all test was performed at three different environmental conditions -46 °C, +21 °C and +66 °C. The tolerance for all test temperatures is \pm 6 °C (\pm 10 °F).

2. Acceptance criteria and test specification

Table 1. Acceptance criteria.

Test	Temperature, °C	Acceptance criteria	Product	Specified test value	Unit
Axial impact	+66 ± 6	No damages or	BEWI	1627	Joules
	+21 ± 6	ovality in the	Smart	1627	Joules
	-46 ± 6	connection's	protector	814	Joules
Angular	+66 ± 6	thread and seal	5" – 5 ½"	814	Joules
impact (45°)	+21 ± 6	after the impact		814	Joules
	-46 ± 6		PIN and BOX	407	Joules
Lateral impact	+21 ± 6		5" – 5 ½" PIN	814	Joules
Vibration	+21 ± 6	Do not fall of or loose	5" – 5 ½" PIN	One-million-cycle test Minimum 900 r/min	
Stripping	+66 ± 6 +21 ± 6 -46 ± 6	No deformation on the protectors	5" – 5 ½" PIN	60 x W (W = Pipe mass)	Pound force

Axial impact: To be considered as approved, the connection must not present any damages after the impact testing at any of the three test temperatures, even if the protector is destroyed.

Angular and lateral impact: To be considered as approved, the connection must not present any damage and ovality after the impact at any of the three test temperatures, even if the protector is destroyed.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 4 av of 21 Dato Date 11.06.2021



Vibration: During transportation pipes are carried by road on the back of a trainer, thread protectors are submitted to vibration loading. Under these condition protectors must remain screwed to continue to provide an optimum protection. The protector must not fall of or loose during testing.

Stripping test: Protector thread may show signs of stress but shall not be torn away. BEWI Smart protectors have no threads.

Torque test is not applicable for this product, because the product has no threads.

3. Reference Documents

Table 2. Reference documents

ldent.	Name
BEWI Test procedure	Performance test procedure. BEWI Smart universal protectors. Testing at BEWI Norplasta AS 27.05.2021
API 5CT 9-th edition ANNEX I	Specification for casing and tubing. Requirements for thread protector design validation
NS-EN ISO 11960:2014 ANNEX I	Petroleum and natural gas industries. Steel pipes for use as casing or tubing for wells. Requirements for thread protector design validation
MIL-STD-810	Environmental engineering considerations and laboratory tests

4. Test Procedure

4.1 Test samples

Tread protectors was made-up on short pipe samples. The made-up test pieces were stabilized at the test temperature and then tested with conditions and procedures described in table 1 and in chapter 4.

4.2 Exposure to temperature before testing

4.2.1 Equipment and conditions

- Freezer
- Hot cabinet
- Calibrated thermometer calibrated by Impex Produkter as (C42)
- Exposure temperatures
 - o -46 ± 6 °C
 - 21 °C ± 6 °C (Room temperature)
 - o 66 °C ± 6 °C
- Exposure time: Minimum 30 minutes
- Max time out of freezer or hot cabinet before testing: 4 minutes

To ensure that the protectors have been completely acquired the temperature the piece was exposed at the required temperature for at least 30 minutes before testing according to table 1 and chapter 4.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 5 av of 21 Dato Date 11.06.2021






Picture 1. PIN and BOX in hot cabinet before testing.

4.3 Axial impact test

4.3.1 Equipment

- Steel metal bar: Diameter 38 mm
- Guillotine that reproduce requested energy
 H (cm)= (^E/_{m*g})*100



Picture 2. Axial testing.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 6 av of 21 Dato Date 11.06.2021



4.3.2 Procedure

For the tests it has been used a guillotine that reproduces the requested energy. The sample was placed in a vertical position, with the thread and the protector in the upper part. The impact was done in the middle of the protector. See picture 2 and 3.



Picture 3. Axial testing with PIN protector.

Angular impact test

4.4.1 Equipment


- Flat steel plate
- Guillotine that reproduce requested energy
 H (cm)= (^E/_{m*g})*100





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 7 av of 21 Dato Date 11.06.2021





Picture 4. Angular testing.

4.4.2 Procedure

For angular impact it has been employed a flat steel plate. The sample was placed in a 45° angle position, with the protector in the upper part. The impact was done in the face of the protector. The impact was performed with a flat steel plate. See picture 4 and 5.



Picture 5. Angular testing with BOX protector.





Rapportnr. Report no. 100093
Revisjonsnr Rev.nr. Side Page 8 av of 21
Dato Date 11.06.2021



4.5 Vibration test

4.5.1 Equipment

- Vibration equipment:
 - o 1460 r/min
 - o Vertical displacement of 8,4 mm
 - o Minimum acceleration of four times gravitational acceleration

4.5.2 Procedure

The vibration testing was done accordance with MIL-STD-810. The protector must not fall of or out during a one-million-cycle test.



Picture 6. Vibration test.

4.6 Stripping test

4.6.1 Equipment

- Test equipment and jigg in accordance with IADC/SPE 11396. See picture 7.
- Applies the protector as required and it was rotated 90°
- Test speed when removing the protector: 2,4 mm/sec





Rapportnr. Report no. 100093

Revisjonsnr Rev.nr. Side Page 9 av of 21
Dato Date 11.06.2021





Picture 7. Stripping test equipment.

4.6.2 Procedure

Stripping test was done accordance with IADC/SPE 11396 on the protector with an axial load equal to or greater than Fax = 0,18 x vm where Fax is the force, expressed in kilonewtons; vm is the linear mass of the pipe, expressed in kilograms per meter; or Fax = 60 x W where Fax is the force, expressed in pounds force; w is the linear mass of the pipe, expressed in pounds per foot. Protector was removed from the jigg. Force was recorded.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 10 av of 21 Dato Date 11.06.2021



5. Results

5.1 Axial impact test

Table 3. Results. Axial impact test.

Product	Test	Angle of	Energy	Results
	temperature, °C	impact, °	applied, J	2,
5 ½" PIN protector	66 ± 6	90	1627	No damages of connection seal and coupling thread area
5 ½" PIN protector	21 ± 6	90	1627	No damages of connection seal and coupling thread area
5 ½" PIN protector	-46 ± 6	90	814	No damages of connection seal and coupling thread area
5 ½" BOX protector	66 ± 6	90	1627	No damages of connection seal and coupling thread area
5 ½" BOX protector	21 ± 6	90	1627	No damages of connection seal and coupling thread area
5 ½" BOX protector	-46 ± 6	90	814	No damages of connection seal and coupling thread area



Picture 8. PIN protector after axial impact. 21 °C.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 11 av of 21 Dato Date 11.06.2021





Picture 9. PIN protector after axial impact. 66 °C.



Picture 10. PIN protector after axial impact. -46 °C.





Rapportnr. Report no. 100093

Revisjonsnr Rev.nr. Side Page 12 av of 21
Dato Date 11.06.2021





Picture 11. PIN protector after testing.




Picture 12. After testing. No damages.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 13 av of 21 Dato Date 11.06.2021





Picture 13. After testing. No damages.



Picture 14. BOX protector after axial impact. 66 °C.






Rapportnr. Report no. 100093

Revisjonsnr Rev.nr. Side Page 14 av of 21
Dato Date 11.06.2021





Picture 15. BOX protector after axial testing.



Picture 16. BOX protector after axial impact. -46 °C.





Rapportnr. Report no. 100093

Revisjonsnr Rev.nr. Side Page 15 av of 21
Dato Date 11.06.2021





Picture 17. After testing. No damages.

5.2 Angular impact test

Table 4. Results. Angular impact test.

Product	Test temperature, °C	Angle of impact, °	Energy applied, J	Results
5 ½" PIN protector	66 ± 6	45	814	No damages or ovality of connection seal and coupling thread area
5 ½" PIN protector	21 ± 6	45	814	No damages or ovality of connection seal and coupling thread area
5 ½" PIN protector	-46 ± 6	45	407	No damages or ovality of connection seal and coupling thread area
5 ½" BOX protector	66 ± 6	45	814	No damages or ovality of connection seal and coupling thread area
5 ½" BOX protector	21 ± 6	45	814	No damages or ovality of connection seal and coupling thread area
5 ½" BOX protector	-46 ± 6	45	407	No damages or ovality of connection seal and coupling thread area




Rapportnr. Report no. 100093

Revisjonsnr Rev.nr. Side Page 16 av of 21
Dato Date 11.06.2021





Picture 18. PIN protector after angular impact. 21 °C




Picture 19. PIN protector after angular impact. -46 °C.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 17 av of 21 Dato Date 11.06.2021





Picture 20. BOX protector after angular impact. 21 °C.




Picture 21. BOX protector after angular impact. -46 °C.





Rapportnr. Report no. 100093 Revisjonsnr Rev.nr. -Side Page 18 av of 21 Dato Date 11.06.2021





Picture 22. After testing. No damages or ovality.



Picture 23. After testing. No damages or ovality.





Rapportnr. Report no. 100093


Revisjonsnr Rev.nr. Side Page 19 av of 21
Dato Date 11.06.2021



5.3 Lateral impact test

Table 5. Results. Lateral impact test.

Product	Test temperature, °C	Angle of impact, °	Energy applied, J	Results
5 ½" PIN protector	21 ± 6	90	814	No damages or ovality of connection seal and coupling thread area



Picture 24. Lateral impact test of PIN protector.

5.4 Vibration

The protector did not fall off or move during a one-million-cycle test. See picture 25.






Rapportnr. Report no. 100093

Revisjonsnr Rev.nr. - Side Page 20 av of 21 Dato Date 11.06.2021





Picture 25. PIN protector after vibration testing.

5.5 Stripping test

Table 6. Results. Stripping test

Product	Test temperature, °C	Height, mm	Force to remove protector, N	
5 ½" PIN protector	66 ± 6	256	810	
5 ½" PIN protector	21 ± 6	256	975	
5 ½" PIN protector	-46 ± 6	253	2190	
5 1/2" BOX protector	66 ± 6	319	713	
5 1/2" BOX protector	21 ± 6	319	1073	





Rapportnr. Report no. 100093
Revisjonsnr Rev.nr. Side Page 21 av of 21
Dato Date 11.06.2021



6. Summary of the results

Table 7. Summary of the results

Test	-46 °C ± 6 °C		21 °C :	±6°C	66 °C ± 6 °C	
	5 ½" PIN	5 ½" BOX	5 ½" PIN	5 ½" BOX	5 ½" PIN	5 1/2" BOX
Axial impact	OK	OK	OK	OK	OK	OK
Angular impact (45°)	OK	OK	OK	OK	OK	OK
Lateral impact	NA	NA	OK	NA	NA	NA
Vibration	NA	NA	OK	NA	NA	NA
Stripping*	2190 N	NA	975 N	1073 N	810 N	713 N

^{*} Stripping test: The criteria are that the protector thread may show signs of stress but shall not be torn away. BEWI Smart protectors have no threads and with this product pull resistance is the same over a longer pull as opposed to protectors with threads that loosen slightly during transport and lose their pull resistance after loosening.

Torque test is not applicable for this product, because the product has no threads.





Rapportnr. Report no. 100093 Revisjonsnr. Rev.nr. -Vedlegg Appendix 1 Dato Date 11.06.2021



{Empty page}